

ProKnow Knowledge Skills Checklist for Contouring Performance-Based Items

- 1. Log in to mdcb.proknow.com
- 2. Choose the "Spine_01_contouring" data set for contouring practice.
- 3. Choose the "Structures" tab
- 4. Select "Edit Structure Set" in the top right of the window
- 5. Identify the bounding box if one is referenced in the question. Remember that additional contouring superiorly or inferiorly past the bounding box will NOT be penalized.
- 6. Adjust window leveling as necessary for contouring accuracy
- 7. Highlight the structure labeled "structure" to begin contouring. DO NOT create any new structures for contouring
- 8. Contouring can be done with the DRAW tool with or without smooth lines turned on
- 9. Contouring can be done with the PAINT tool with any brush diameter chosen
- 10. Erase unwanted portions of the contour with draw/paint tool
- 11. To create more than one contour per slice or create a hole in an existing contour, hold down the 'Shift' or 'Alt' key and draw/paint outside or inside the existing contour
- 12. Interpolate between slices
- 13. Copy from Inferior/Superior Slice
- 14. Clear Current Slice or Clear all Slices
- 15. When finished select "Commit" twice to finalize and submit contour